


THE FUTURE IS BUILT SAFELY

- ALWAYS USE
SHADES
11-13.
- MAINTAIN
PROPER PPE
AT ALL TIMES.
- ALWAYS
HAVE PROPER
VENTILATION.
- ONLY YOU
CAN PREVENT
ACCIDENTS.
BEWARE OF
ELECTRICITY.

A SAFE,
WORK
READY
WELDER

NOTE HIS:

- APPROPRIATE
HELMET USAGE
- PROPER
GLOVES
(LEATHER)
- GOOD ANGLE OF
ATTACK (WORK
ANGLE)
- HAND
RETURNING TO
STINGER
- AWARE OF
WELDING LEAD



AMERICAN WELDING SOCIETY

BY
DOMINIC
PIMENTEL-CTEC

