


# WELDING SAFETY


## SAFETY RULES

1. WEAR A WELDING HELMET AT ALL TIMES
2. USE GLOVES AND FLAME RESISTANT CLOTHING
3. KEEP YOUR WORK AREA CLEAN
4. CHECK EQUIPMENT BEFORE WELDING
5. NEVER WELD NEAR FLAMMABLE MATERIALS



## HAZARDS

1. BURNS FROM HOT METAL
2. EYE DAMAGE FROM ARC FLASH
3. ELECTRIC SHOCK
4. TOXIC FUMES
5. FIRE HAZARDS



## PPE (PERSONAL PROTECTIVE EQUIPMENT)



1. WELDING HELMENT
2. SAFTEY GLASSES
3. WELDING GLOVES
4. LEATHER JACKET
5. STEEL TOE BOOTS

