

Welding Safety/PPE

Carter Bumgardner: Springfield-Clark CTC



PPE stands for Personal Protective Equipment. It is a specialized clothing or gear worn to minimize exposure to hazards that cause injuries or infections.

Welding PPE includes:

Welding Helmet With Correct Shade(7-14)

Welding Gloves

Flame-Resistance Clothing

Safety Glasses

Steel Toe Boots

Ear Protection

Respirator



These pieces of PPE apply to all types of welding including:

SMAW

GMAW

GTAW

FCAW

