

Oxy-fuel Cutting

Dylan Harwood
Ethan Turner



PPE Needed

Safety glasses
Work Boots
Longsleeves
Work Gloves

Keep flame
pointed away
from you and
others

Turn gas
bottles off
when you
finish




Turn on bottles
Set regulators
Oxygen 40psi
Acetylene 8psi
Set acetylene
On your torch
Use striker
Adjust oxygen
Preheat metal

Torch Ettiquette



Tools and equipment



Striker Oxy-fuel setup

Step by Step Process

