

# Welding PPE

## Personal Protective Equipment

Colton  
Springer

### Welding Helment

Protects the eyes, face, and neck from UV radiation and flying debris.



### Flame-Resistant Clothing

Protects skin from sparks and intense heat, often made of leather or treated cotton



### Welding Gloves/Gauntlets

Insulated to protect hands from burns, molten metal, and electric.



### Respirators

Protects lungs from dangerous fumes and gases. Safety



### Glasses/Goggles

Worn under the helmet for added eye protection.



### Ear Protection

Ear muffs or plugs to protect against noise.

