


Evan Martin Springfield Clark CTC




A soldering iron can go to temperatures over 300°C. Never touch the tip and always place the iron back in its stand when not in use. Always wear your safety glasses and other proper protection.


Soldering Safety

Get a temperature-controlled iron is best for your electronics. Always keep the iron tip shiny clean. Use clips hold your circuit board or wires in place so you can use both hands for a more easy way to solder.

Soldering Setup



How to Do Soldering



Touch the iron tip to both areas you want to apply the hot metal to the circuit board. Once you have it soldered on there take the iron tip off the area you just soldered.